




Front view



(3) Side view  
of  
Brush Guard




Twist  
Pin  
Assembly  
(1)  
Engaged



(2) mounting  
Bracket

Truck side Push Plates




Existing Plates  
that remain  
on a truck  
after a snowplow  
is removed.




Page 7 of 7

Back view



(10)  
Twist P.N  
Assembly  
NOT Engaged



Top view

